



AS 355 TWINSTAR REVISION STATUS
FAA CERTIFICATION

REVISED: 11/02/2022

AIRCRAFT: AS355E-F-F1-F2-N-NP

| <u>MANUAL</u> | <u>CODE</u> | <u>REVISION</u> | <u>REV DATE</u> |
|---------------------------------------|-------------|------------------|-----------------|
| DESCRIPTION & OPERATION MANUAL | MDF | 9 | 09-20-21 |
| MASTER SERVICING MANUAL | MSM | | |
| F CHAP 4 | | 11 | 09-13-21 |
| F CHAP 5 | | 12 | 09-13-21 |
| F1 CHAP 4 | | 11 | 09-13-21 |
| F1 CHAP 5 | | 12 | 09-13-21 |
| F2 CHAP 4 | | 12 | 09-13-21 |
| F2 CHAP 5 | | 12 | 09-13-21 |
| N CHAP 4 | | 11 | 09-13-21 |
| N CHAP 5 | | 12 | 09-13-21 |
| NP CHAP 4 | | 10 | 09-13-21 |
| NP CHAP 5 | | 12 | 09-13-21 |
| MAINTENANCE MANUAL | MET | 9 | 09-20-21 |
| STRUCTURAL REPAIR MANUAL | MRS | 8 | 09-20-21 |
| REPAIR MANUAL - TRANSMISSION SYSTEM | MRM | 9 | 09-20-21 |
| STORAGE MANUAL | MST | 9 | 09-20-21 |
| ILLUSTRATED PARTS CATALOG E-F-F1-F2-N | IPC | 5 | 09-21-20 |
| ILLUSTRATED PARTS CATALOG NP | IPC | 6 | 09-20-21 |
| TOOL CATALOG (except NP) | ICO | 6 | 09-20-21 |
| TOOL CATALOG NP VERSION | ICO | 6 | 09-20-21 |
| FAULT ISOLATION MANUAL | MFI | 6 | 09-20-21 |
| WIRING DIAGRAMS MANUAL | MCS | 8 | 09-20-21 |
| INDEX OF MODIFICATIONS | SIM | 9 | 09-20-21 |
| STANDARD PRACTICES MANUAL | MTC | 11 | 07-21-22 |
| FLIGHT MANUAL "ALL VERSIONS" | PMV | SEE SEPARATE SRD | |
| SERVICE BULLETINS | SBT | SEE INDEXES | |
| INFORMATION NOTICES | IN | SEE INDEXES | |
| O.R.I.O.N. LIGHT USB KEY | ORIL | 6.01 | 03-25-19 |
| COMPONENT MAINTENANCE MANUAL USB | ECMM | 31 | 06-08-22 |
| INFORMATION NOTICE CD-ROM | | 8 | 01-01-15 |

**FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2022
355 TWINSTAR

REVISED: 11-18-2022

AIRFRAME SERVICE BULLETINS

SAFETY INFORMATION NOTICE

| <u>S/B</u> | <u>DATED</u> | <u>I/N</u> | <u>DATE</u> |
|------------------------------|--------------|----------------------|-------------------|
| ASB 01-00-24 RN 1 | 22-13 | 2145-I-28 RN5 | 06/03/2022 |
| ASB 01-22-24 RN1 | 22-12 | 2302-I-00 RN2 | 02/23/2022 |
| ASB 05-00-14 RN1 | 22-11 | 3041-I-00 RN2 | 03/29/2022 |
| ASB 05-00-56 RN1 | 21-51 | 3458-I-00 RN3 | 12/09/2021 |
| ASB 05-00-79 RN1 | 22-22 | 3586-I-00 RN2 | 05/18/2022 |
| ASB 05-00-58 RN2 | 22-11 | 3629-I-25 RN0 | 07/29/2022 |
| ASB 05-00-68 ERR1 (09-20-22) | 22-29 | 3643-I-00 RN1 | 05/03/2022 |
| ASB 05-00-88 RN0 | 22-13 | 3652-I-31 RN1 | 05/16/2022 |
| ASB 05-00-88 RN1 | 22-29 | 3678-I-31 RN0 | 05/16/2022 |
| ASB 05-00-80 RN1 | 21-51 | 3686-I-00 RN2 | 10/17/2022 |
| ASB 25-01-35 RN0 | 22-18 | 3707-I-00 RN0 | 05/09/2022 |
| ASB 25-01-38 RN0 (10-04-22) | 22-40 | 3770-I-00 RN0 | 03/28/2022 |
| ASB 25-01-38 ERR | 22-40 | 3718-I-00 RN0 | 12/02/2021 |
| ASB 25-01-39 RN0 | 22-40 | 3795-I-71 RN0 | 05/23/2022 |
| EASB 05-00-62 RN2 | 21-47 | 3815-I-00 RN0 | 10/04/2022 |
| EASB 67-00-49 RN0 | 22-18 | 3703-P-00 RN0 | 06/30/2022 |
| SBT 00-00-02 RN2 | 22-13 | 3632-P-56 RN1 | 12/03/2021 |
| SBT 00-00-02 RN2 | 22-12 | 3821-P-00 RN0 | 09/23/2022 |
| SBT 05.00.24 RN2 | 01-22 | 3123-S-00 RN1 | 04/12/2022 |
| SBT 05-00-61 RN2 | 22-18 | 3093-S-00 RN2 | 02/18/2022 |
| SBT 29-00-06 RN4 | 22-41 | 3287-S-67 RN1 | 02/18/2022 |
| SBT 31-00-07 ERR | 21-30 | 3754-S-34 RN0 | 01/21/2022 |
| SBT 52-00-24 RN3 | 22-25 | 3782-S-34 RN0 | 06/09/2022 |
| SBT 52-00-35 RN0 | 22-39 | 3786-S-62 RN0 | 04/15/2022 |
| SBT 52-00-36 RN0 | 21-51 | 3792-S-05 RN0 | 04/28/2022 |
| SBT 53-00-36 RN0 | 22-22 | | |
| SBT 64-00-07 RN5 | 21-51 | | |
| SBT 79-00-09 RN0 | 22-26 | | |