

Airbus Helicopters Inc. Technical Support 2701 Forum Drive Grand Prairie, TX 75052 January 18, 2017

Subject: Global AMOC for AD 2013-16-14

Attachments: AD 2013-16-14 dated October 9, 2013

AMOC for AD 2013-16-14 dated January 18, 2017 ASB EC135-63A-017 Rev 2 dated December 5, 2016

To all EC135 Operators,

On October 9, 2013, AD 2013-16-14 was issued for the Eurocopter Helicopter EC135 covering the P1, P2, P2+, T1, T2, and T2+ models.

In Paragraph (e)(2) Required Actions (1) Within 4,000 hours, time-in-service or at the next main transmission repair or overhaul, whichever occurs first, machine the main transmission housing upper part in accordance with Annex A of ZF Luftharttechnik GmbH Service Instruction No. EC135FS108-1659-1009, dated September 14, 2010.

The FAA has granted the attached AMOC as of January 18, 2017 to eliminate this requirement at 4,000 hours in accordance with ASB EC135-63-017 Rev 2 that has extended the requirement to machine the upper case no later than 5150 flight hours or at the next major repair or overhaul.

This letter is to bring to our customer's attention that this 4000 hour requirement has been canceled with the attached AMOC. For any questions on this issue please contact Dave Vogel.

Office PH 972-641-3573 Cell PH 817-201-1196 dave.vogel@airbus.com

Larry Huntley

Director, Technical Support Airbus Helicopters Inc.

WK PH 972-641-5204 FAX 972-641-3710

Email: larry.huntley@airbus.com

www.airbus.com