



American Eurocopter Corp.  
Technical Support  
2701 Forum Drive  
Grand Prairie, TX 75052

December 13, 2013

**Subject: Global AMOC for AD 2013-21-05**

Attachments: AD 2013-21-05 dated October 31, 2013

AMOC for AD 2013-21-13 dated December 5, 2013

Alert Service Bulletin EC135-67A-012 Rev 01 dated October, 19, 2006

To all EC135 Operators,

On Thursday October 31, 2013, AD 2013-21-05 was issued for the Eurocopter Helicopter EC135 covering the P1, P2, P2+, T1, T2, and T2+ models.

In Paragraph (e) **Required Actions (1)** Within 100 hours, time-in-service (tis) and thereafter at intervals not to exceed **800 hours TIS**, inspect each bearing for freedom of movement by turning and tilting the bearing as depicted in Figure 2 of Eurocopter Alert Service Bulletin No. EC135-67A-012 Rev1, dated October 18, 2006 (ASB)

The FAA has granted the attached AMOC as of December 5, 2013 to increase the 800 hour periodical inspection requirement from 800 hours to the new requirement of **1000 hours**.

The letter is to bring to our customer's attention that this time limit has been increased with the release of the MSM Rev 016a dated April 26, 2013 in section **05-24-00, 6-1 Periodical Inspection – Inspection**.

Best Regards,

Mark Jones  
Director, Technical Support  
American Eurocopter Corp.  
WK PH 972-641-5204  
FAX 972-641-3710  
Email: [mark.jones@eurocopterusa.com](mailto:mark.jones@eurocopterusa.com)  
[www.eurocopterusa.com](http://www.eurocopterusa.com)