



AS 355 TWINSTAR REVISION STATUS
FAA CERTIFICATION

REVISED: 10-12-2023

AIRCRAFT: AS355E-F-F1-F2-N-NP

| <u>MANUAL</u> | <u>CODE</u> | <u>REVISION</u> | <u>REV DATE</u> |
|--|-------------|------------------|-----------------|
| DESCRIPTION & OPERATION MANUAL | MDF | 9 | 09-20-21 |
| MASTER SERVICING MANUAL | MSM | | |
| F CHAP 4 | | 12 | 07-10-23 |
| F CHAP 5 | | 13 | 07-10-23 |
| F1 CHAP 4 | | 12 | 07-10-23 |
| F1 CHAP 5 | | 13 | 07-10-23 |
| F2 CHAP 4 | | 13 | 07-10-23 |
| F2 CHAP 5 | | 13 | 07-10-23 |
| N CHAP 4 | | 12 | 07-10-23 |
| N CHAP 5 | | 13 | 07-10-23 |
| NP CHAP 4 | | 11 | 07-10-23 |
| NP CHAP 5 | | 13 | 07-10-23 |
| E CHAP 4 | | 13 | 07-10-23 |
| E CHAP 5 | | 12 | 07-10-23 |
| MAINTENANCE MANUAL | MET | 10 | 07-10-23 |
| STRUCTURAL REPAIR MANUAL | MRS | 9 | 07-10-23 |
| REPAIR MANUAL - TRANSMISSION SYSTEM | MRM | 10 | 07-10-23 |
| STORAGE MANUAL | MST | 10 | 07-10-23 |
| ILLUSTRATED PARTS CATALOG E-F-F1-F2-N | IPC | 5 | 09-21-20 |
| ILLUSTRATED PARTS CATALOG NP | IPC | 7 | 07-10-23 |
| TOOL CATALOG (except NP) | ICO | 6 | 09-20-21 |
| TOOL CATALOG NP VERSION | ICO | 6 | 09-20-21 |
| FAULT ISOLATION MANUAL | MFI | 7 | 07-10-23 |
| WIRING DIAGRAMS MANUAL | MCS | 8 | 09-20-21 |
| INDEX OF MODIFICATIONS | SIM | 9 | 09-20-21 |
| STANDARD PRACTICES MANUAL | MTC | 11 | 07-21-22 |
| FLIGHT MANUAL "ALL VERSIONS" | PMV | SEE SEPARATE SRD | |
| SERVICE BULLETINS | SBT | SEE INDEXES | |
| INFORMATION NOTICES | IN | SEE INDEXES | |
| O.R.I.O.N. LIGHT USB KEY | ORIO | 10.0 | 09-18-23 |
| COMPONENT MAINTENANCE MANUAL USB | ECMM | 31.1 | 06-19-23 |
| INFORMATION NOTICE CD-ROM | | 8 | 01-01-15 |

**FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2023
355 TWINSTAR

REVISED: 11-09-2023

AIRFRAME SERVICE BULLETINS

| <u>S/B</u> | <u>DATED</u> | <u>I/N</u> | <u>DATE</u> |
|-------------------------|--------------|---------------|-------------|
| ASB 05-00-87 RNO | 23-04 | 3586-I-00 RN3 | 06/20/2023 |
| ASB 05-00-87 ERERR1 | 23-05 | 3731-I-25 RN1 | 12/15/2022 |
| ASB 05-00-91 RNO | 22-49 | 3764-I-28 RNO | 09/06/2023 |
| SBT 05-00-90 RNO | 22-50 | 3848-I-25 RNO | 12/14/2022 |
| SBT 25-00-58 RN5 | 23-42 | 3875-I-00 RNO | 02/09/2023 |
| SBT 25-01-31 RN1 | 23-27 | 3928-I-00 RNO | 08/21/2023 |
| SBT 25-01-40 RNO | 22-49 | 3915-I-67 RNO | 07/27/2023 |
| SBT 32-00-11 ERERR1 | 22-27 | 3821-P-00 RN1 | 02/14/2023 |
| SBT 52-00-38 ERO | 23-24 | 3862-P-00 RNO | 01/06/2023 |
| | | 3700-S-00 RN2 | 09/18/2023 |
| | | 3749-S-00 RNO | 02/06/2023 |
| | | 3749-S-00 RN1 | 02/08/2023 |
| | | 3868-S-20 RNO | 02/22/2023 |
| | | 3887-S-00 RNO | 04/20/2023 |
| | | 3947-S-00 RNO | 10/11/2023 |