



**BO 105LS REVISION STATUS
FAA CERTIFICATION**

REVISED: 09-27-21

TYPE OF AIRCRAFT: BO 105LS

| <u>MANUAL</u> | | <u>REVISION</u> | <u>DATED</u> | <u>RUSH</u> | <u>DATED</u> |
|----------------------------------|---------|-----------------|------------------|-------------|--------------|
| LOAP | PART 1 | ISS 17 | 11-16-16 | | |
| | PART 2 | ISS 3 | 02-27-16 | | |
| | PART 3 | ISS 3 | 09-20-17 | | |
| MAINTENANCE MANUAL (M/M) | | 7 | 03-28-19 | | |
| REPAIR MANUAL (REM) | | | | | |
| | REM 106 | 6 | 07-01-12 | | |
| | REM 301 | 4 | 07-01-12 | | |
| | REM 308 | 4 | 07-01-12 | | |
| | REM 403 | 1 | 07-15-93 | 01/05 | 06/06/05 |
| ILLUSTRATED PARTS CATALOG (IPC) | | 7 | 04-01-15 | | |
| WIRING DIAGRAM MANUAL (WDM) | | 2 | 08-10-07 | | |
| SERVICE BULLETINS | | | SEE INDEXES | | |
| SERVICE LETTERS | | | SEE INDEXES | | |
| FLIGHT MANUAL | | | SEE SEPARATE SRD | | |
| INDOC - CD-ROM | | 5 | 07-01-15 | | |
| STANDARD PRACTICES MANUAL | | 10 | 07-21-21 | | |

**FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND SERVICE LETTERS ISSUED IN 2021
BO 105LS

REVISED: 11-17-2021

AIRFRAME SERVICE BULLETINS

S/B

DATED

SAFETY INFORMATION NOTICES

S/L

DATE

| | |
|----------------------|-----------------|
| 2046-I-00 RN1 | 03-05-21 |
| 2152-S-00 RN2 | 02-17-21 |
| 2273-S-64 RN2 | 03-15-21 |
| 2633-S-62 RN1 | 05-19-21 |
| 2867-I-00 RN2 | 07-28-21 |
| 3000-I-00 | 6-22-21 |
| 3123-S-00 | 09-28-21 |
| 3157-S-63 RN1 | 03-30-21 |
| 3170-S-00 RN2 | 02-26-21 |
| 3400-P-00 RN1 | 08-30-21 |
| 3401-I-00 | 02-25-21 |
| 3401-I-00 RN1 | 03-22-21 |
| 3447-I-00 RN1 | 02-09-21 |
| 3463-S-00 RN2 | 09-28-21 |
| 3476-I-12 RN2 | 04-06-21 |
| 3492-I-25 RN6 | 03-30-21 |
| 3586-I-00 | 12-10-20 |
| SPN 3587-P-00 | 12-07-20 |
| SPN 3632-P-56 | 06-03-21 |
| 3613-S-00 RN1 | 02-12-21 |
| 3626-P-00 | 02-04-21 |
| 3634-I-00 | 03-04-21 |
| 3640-P-00 | 05-07-21 |
| 3643-I-00 | 02-09-21 |
| 3654-P-00 RN0 | 07-19-21 |
| 3700-S-24 | 07-12-21 |
| 3717-S-71 | 10-14-21 |