



## EC130 REVISION STATUS

REVISED: 11-02-2022

TYPE OF AIRCRAFT: EC130

<u>MANUAL</u>	<u>CODE</u>	<u>REVISION</u>	<u>DATED</u>	<u>RUSH</u> <u>REVISION</u>	<u>DATED</u>
MASTER SERVICING MANUAL	MSM				
B4 Chapter 4		12	04-05-21		
B4 Chapter 5		21	05-23-22		
T2 Chapter 4		10	04-05-21		
T2 Chapter 5		18	05-23-22		
MAINTENANCE MANUAL B4 - T2	AMM	20	05-23-2022		
ILLUSTRATED PARTS CATALOG B4	IPC	10	05-23-2022		
ILLUSTRATED PARTS CATALOG T2	IPC	10	05-23-2023		
SYSTEM DESCRIPTIONS MANUAL B4 - T2	SDS	20	05-23-2022		
STRUCTURAL REPAIR MANUAL	SRM	6	11-01-21		
WIRING DIAGRAM MANUAL B4 - T2	WDM	20	05-23-2022		
INDEX OF MODIFICATIONS B4 - T2	SIM	14	05-23-2022		
<b>STANDARD PRACTICES MANUAL</b>	<b>MTC</b>	<b>11</b>	<b>07-21-22</b>		
ORION LIGHT USB	ORIL	16	07-04-2022		
COMPONENT MAINTENANCE MANUAL USB	ECMM	31	06-08-2022		
SERVICE LETTER CD-ROM	IN	ISSUE 5	01-01-10		
FLIGHT MANUAL	FLM	SEE SEPARATE SRD			
SERVICE BULLETINS	SBT	SEE INDEXES			
SERVICE LETTERS	IN	SEE INDEXES			

\*\*FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

**SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2022**  
**EC130**

**REVISED: 12/16/2022**

**AIRFRAME SERVICE BULLETINS**

<u>S/B</u>	<u>DATED</u>	<u>I/N</u>	<u>DATE</u>	<u>IN</u>	<u>DATE</u>
ASB 05A028 RN1	5/30/2022	2145-I-28 RN5	06/03/2022		
ASB 05A041 RN0	7/20/2022	2303-I-00 RN 2	02/23/2022		
ASB 32A013 ERR	22-07	3041-1-00 RN2	03/29/2022		
ASB 76A009 RN0	22-25	3458-I-00 RN3	12/09/2021		
ASB 76A010 RN0	22-25	3586-I-00 RN2	05/18/2022		
ASB 76A011 ERR	22-08	3629-I-25 RN0	07/29/2022		
ASB 76A011 RN1	22-26	3643-I-00 RN1	05/03/2022		
EASB 05A039 RN1	21-50	3652-I-31 RN1	05/16/2022		
EASB 05A039 RN2	22-06	<b>3665-I-00 RN1</b>	<b>12/01/2022</b>		
EASB 32A013	22-07	3678-I-31 RN0	05/16/2022		
EASB 67A023 RN0	22-18	3686-I-00 RN1	02/21/2022		
EASB 76A011 RN0	22-04	3686-I-00 RN2	10/17/2022		
EASB 76A012 RN0	22-04	3707-I-00 RN0	05/09/2022		
SBT 00-002 RN2	22-12	3715-I-80	02/07/2022		
SBT 05-012 RN1	22-06	3718-I-00	12/02/2021		
SBT 52-025 RN0	22-39	3748-I-21	02/02/2022		
SBT 05-026 RN2	22-16	3761-I-00 RN0	05/03/2022		
SBT 05-034 RN1	22-08	3809-I-00 RN0	06/07/2022		
<b>SBT 26-003 RN0</b>	<b>22-47</b>	3815-I-00 RN0	10/04/2022		
SBT 28-017 RN0	22-36	3834-I-21 RN0	10/17/2022		
SBT 32-008 RN2	22-10	3024-P-00 RN6	11/10/2022		
SBT 53-036 RN5	21-50	3433-P-24 RN1	11/23/2022		
SBT 53-045 RN0	22-22	3632-P-56 RN1	12/03/2021		
SBT 63-002 RN1	22-36	3703-P-00 RN0	06/30/2022		
SBT 63-022 RN0	22-11	3821-P-00 RN0	09/23/2022		
SBT 76-006 RN2	22-04	3700-S-24 RN1	03/21/2022		
SBT 76-008 RN1	21-04	3093-S-00 RN2	02/18/2022		
		3123-S-00 RN1	04/12/2022		
		3754-S-34	01/21/2022		
		3782-S-34 RN0	06/09/2022		
		3786-S-62	04/15/2022		