



AS 355 TWINSTAR REVISION STATUS
FAA CERTIFICATION

REVISED: 11/02/2022

AIRCRAFT: AS355E-F-F1-F2-N-NP

<u>MANUAL</u>	<u>CODE</u>	<u>REVISION</u>	<u>REV DATE</u>
DESCRIPTION & OPERATION MANUAL	MDF	9	09-20-21
MASTER SERVICING MANUAL	MSM		
F CHAP 4		11	09-13-21
F CHAP 5		12	09-13-21
F1 CHAP 4		11	09-13-21
F1 CHAP 5		12	09-13-21
F2 CHAP 4		12	09-13-21
F2 CHAP 5		12	09-13-21
N CHAP 4		11	09-13-21
N CHAP 5		12	09-13-21
NP CHAP 4		10	09-13-21
NP CHAP 5		12	09-13-21
MAINTENANCE MANUAL	MET	9	09-20-21
STRUCTURAL REPAIR MANUAL	MRS	8	09-20-21
REPAIR MANUAL - TRANSMISSION SYSTEM	MRM	9	09-20-21
STORAGE MANUAL	MST	9	09-20-21
ILLUSTRATED PARTS CATALOG E-F-F1-F2-N	IPC	5	09-21-20
ILLUSTRATED PARTS CATALOG NP	IPC	6	09-20-21
TOOL CATALOG (except NP)	ICO	6	09-20-21
TOOL CATALOG NP VERSION	ICO	6	09-20-21
FAULT ISOLATION MANUAL	MFI	6	09-20-21
WIRING DIAGRAMS MANUAL	MCS	8	09-20-21
INDEX OF MODIFICATIONS	SIM	9	09-20-21
STANDARD PRACTICES MANUAL	MTC	11	07-21-22
FLIGHT MANUAL "ALL VERSIONS"	PMV	SEE SEPARATE SRD	
SERVICE BULLETINS	SBT	SEE INDEXES	
INFORMATION NOTICES	IN	SEE INDEXES	
O.R.I.O.N. LIGHT USB KEY	ORIL	6.01	03-25-19
COMPONENT MAINTENANCE MANUAL USB	ECMM	31	06-08-22
INFORMATION NOTICE CD-ROM		8	01-01-15

**FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND INFORMATION NOTICES MAILED IN 2022
355 TWINSTAR

REVISED: 12-16-2022

AIRFRAME SERVICE BULLETINS

SAFETY INFORMATION NOTICE

<u>S/B</u>	<u>DATED</u>	<u>I/N</u>	<u>DATE</u>
ASB 01-00-24 RN 1	22-13	2145-I-28 RN5	06/03/2022
ASB 01-22-24 RN1	22-12	2302-I-00 RN2	02/23/2022
ASB 05-00-14 RN1	22-11	3041-I-00 RN2	03/29/2022
ASB 05-00-56 RN1	21-51	3458-I-00 RN3	12/09/2021
ASB 05-00-79 RN1	22-22	3586-I-00 RN2	05/18/2022
ASB 05-00-58 RN2	22-11	3629-I-25 RN0	07/29/2022
ASB 05-00-68 ERR1 (09-20-22)	22-29	3643-I-00 RN1	05/03/2022
ASB 05-00-88 RN0	22-13	3652-I-31 RN1	05/16/2022
ASB 05-00-88 RN1	22-29	3665-I-00 RN1	12/01/2022
ASB 05-00-80 RN1	21-51	3678-I-31 RN0	05/16/2022
ASB 25-01-35 RN0	22-18	3686-I-00 RN2	10/17/2022
ASB 25-01-38 RN0 (10-04-22)	22-40	3707-I-00 RN0	05/09/2022
ASB 25-01-38 ERR	22-40	3770-I-00 RN0	03/28/2022
ASB 25-01-39 RN0	22-40	3718-I-00 RN0	12/02/2021
EASB 05-00-62 RN2	21-47	3795-I-71 RN0	05/23/2022
EASB 67-00-49 RN0	22-18	3815-I-00 RN0	10/04/2022
SBT 00-00-02 RN2	22-13	3433-P-24 RN1	11/23/2022
SBT 00-00-02 RN2	22-12	3703-P-00 RN0	06/30/2022
SBT 05.00.24 RN2	01-22	3632-P-56 RN1	12/03/2021
SBT 05-00-89 RN0	22-43	3821-P-00 RN0	09/23/2022
SBT 05-00-61 RN2	22-18	3123-S-00 RN1	04/12/2022
SBT 26-00-14 RN0	22-47	3093-S-00 RN2	02/18/2022
SBT 29-00-06 RN4	22-41	3287-S-67 RN1	02/18/2022
SBT 31-00-07 ERR	21-30	3754-S-34 RN0	01/21/2022
SBT 52-00-24 RN3	22-25	3782-S-34 RN0	06/09/2022
SBT 52-00-35 RN0	22-39	3786-S-62 RN0	04/15/2022
SBT 52-00-36 RN0	21-51	3792-S-05 RN0	04/28/2022
SBT 53-00-36 RN0	22-22		
SBT 64-00-07 RN5	21-51		
SBT 79-00-09 RN0	22-26		